

3.600 St. Louis County
Westlake SLF

JOHN ASHCROFT
Governor


G. TRACY MEHAN III
Director



STATE OF MISSOURI
DEPARTMENT OF NATURAL RESOURCES
MEMORANDUM

Division of Energy
Division of Environmental Quality
Division of Geology and Land Survey
Division of Management Services
Division of Parks, Recreation,
and Historic Preservation

TO: File
FROM: Joe Trunko, WMPS
DATE: October 10, 1990
SUBJECT: Routine Surveillance at Westlake SLF



On October 4, 1990, I conducted a routine surveillance at the above referenced facility. Mr. Randy Anderson represented the landfill. The purpose of the surveillance was to determine if actions had been taken to correct unsatisfactory features noted in the inspection conducted the previous week. The active face was in the Southeast section of the landfill. Most of the areas of exposed waste as noted in the previous inspection report had been covered satisfactorily with dirt. A small area of exposed waste still remained along the east wall. However, several piles of cover material were stock piled in this area. Mr. Anderson informed me that the area will be covered as soon as possible. No areas of Sanifoam were observed at the time of the surveillance. Mr. Anderson informed me that only a two (2) day supply remained of the sanifoam. Once the supply is exhausted, the facility will resume the use of clay as cover material.

During the previous week, a break had occurred in the line connecting the leachate lagoon to the MSD sewer line. Mr. Anderson informed me that repair of the line had been accomplished.

JT/cc

cc: WMPS

Site:	West Lake SLF
ID:	MBD07990932
Area:	17.8
Date:	10-10-90
By:	CM

40241274



SUPERFUND RECORDS

DNR 0025